


28 446 Massage Shower Head

Exploded View



Parts Breakdown

Pos No.	Spare Part Description	Product No.	Pcs.
	28 446		
1	Bellows	45 199	1
2	Fiber washer for relexa hose	01 389	1
3	Filter screen	06 768	1
4	Ring	45 932	1
5	Rose kit	45 928	1